



**UPPER PATUXENT RIVER WATERSHED RESTORATION ACTION STRATEGY (WRAS)  
FORM 1 -- Catchment Information**

Subwatershed: Upper Patuxent

Location of Catchment Centroid on ADC Map: Year: 2001 Page: 9 Grid: E3

State Plane Coordinates of Outfall Location: X: 1369407 Y: 496205

Closest Road Intersection to Outfall: Scarlet Tanager Loop

Outfall SDI ID or Outfall Description: no SDI ID - drains north to wetland area

Objective: Demonstration / Impairment(s) (Sheet 1) \_\_\_\_\_

Drainage Area (ac): 7.0 Impervious Area (ac): 3.7

Percent Impervious: 53% Soil Recharge Factor (S): 0.13

WQ<sub>v</sub> (required): 0.31 Re<sub>v</sub> (required): 0.04

Predominant Land Use: parking lot Mean Depth to Ground Water: \_\_\_\_\_

Sanitary System:  Septic  Municipal Sewer Water Supply:  On Site Well  Public Water

**Storm Drainage System Within Catchment**

Piped: 100% Open Channels: 0%

Area Drained by System: 100%

Location in Catchment:  Headwaters  Middle  Lower  All

Open Channel Lining- Vegetation: 0% Riprap: 0% Concrete: 0% Other: 0%

**Existing IMP(s) / BMP(s)**

SDI ID: Wetland A Type (number from Sheets 4 & 5): 21 Age: \_\_\_\_\_

Closest Road Intersection to IMP / BMP: Scarlet Tanager Loop

Catchment Area Treated (ac) : 7.0 Percentage Catchment Treated: 100%

WQ<sub>v</sub> Provided:  YES  NO Re<sub>v</sub> Provided:  YES  NO C<sub>p</sub> Provided:  YES  NO

SDI ID: \_\_\_\_\_ Type (number from Sheets 4 & 5): \_\_\_\_\_ Age: \_\_\_\_\_

Closest Road Intersection to IMP / BMP: \_\_\_\_\_

Catchment Area Treated (ac) : \_\_\_\_\_ Percentage Catchment Treated: \_\_\_\_\_

WQ<sub>v</sub> Provided:  YES  NO Re<sub>v</sub> Provided:  YES  NO C<sub>p</sub> Provided:  YES  NO

SDI ID: \_\_\_\_\_ Type (number from Sheets 4 & 5): \_\_\_\_\_ Age: \_\_\_\_\_

Closest Road Intersection to IMP / BMP: \_\_\_\_\_

Catchment Area Treated (ac) : \_\_\_\_\_ Percentage Catchment Treated: \_\_\_\_\_

WQ<sub>v</sub> Provided:  YES  NO Re<sub>v</sub> Provided:  YES  NO C<sub>p</sub> Provided:  YES  NO

**UPPER PATUXENT RIVER WATERSHED RESTORATION ACTION STRATEGY (WRAS)**  
**FORM 1 -- Catchment Information** (concluded)

<b>CATCHMENT SUMMARY</b>	
WQ <sub>v</sub> (provided): _____	Re <sub>v</sub> (provided) : _____
Area Treated (ac): _____	Impervious Area Treated (ac): _____
Area Treated (%): _____	Impervious Area Treated (%): _____

**Comments** \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

## UPPER PATUXENT RIVER WATERSHED RESTORATION ACTION STRATEGY (WRAS) FORM 2 -- Site Information

Site Name: Patuxent Wildlife Refuge Address: Scarlet Tanager Loop  
 Site Owner: U.S. Fish and Wildlife Service  
 State Plane Coordinates of Site Centroid: X: 1369405 Y: 495441 Date: 4/25/03  
 Personnel: PM Weather: overcast, 75F deg  
 Area (ac): 7 Impervious Area (ac): 3.7  
 Percent Impervious: 53% Soil Recharge Factor (S): 0.13  
 WQ<sub>v</sub> (required): 0.31 Re<sub>v</sub> (required): 0.04  
 Property Area (ac): 1012.5 Property Area Included in Site: 1 %  
 Amount of Catchment Occupied by Site: 100 %

### Storm Drainage System Within Site

Piped: 100% Open Channels: 0% Area Drained by System: 100%  
 Open Channel Lining - Vegetation: 0% Riprap: 0% Concrete: 0% Other: 0%

### Existing IMP(s) / BMP(s) (Identified on Page 1, FORM 1, Catchment Information)

SDI ID: Wetland A Condition:  Excellent  Good  Average  Fair  Poor  
 SDI ID: \_\_\_\_\_ Condition:  Excellent  Good  Average  Fair  Poor  
 SDI ID: \_\_\_\_\_ Condition:  Excellent  Good  Average  Fair  Poor

### Site Information

Type of Pavement:  Bituminous  Concrete  Gravel  Grid Pavers  Other \_\_\_\_\_  
 Pavement Condition:  Excellent  Good  Average  Fair  Poor  
 Underdrains can be easily directed to existing storm drains or daylighted:  YES  NO  
 Gutter/Exterior Downspouts Present:  YES  NO  
 Roof Connected Directly to Storm Drain:  YES  NO  
 Roof Drains onto Impervious Surface:  YES  NO  
 Obvious Existing Drainage Problems:  Extensive  Moderate  Average  Limited  None  
 Steep Slopes Present:  Extensive  Moderate  Average  Limited  None  
 Existing Landscaping:  Extensive  Moderate  Average  Limited  None  
 Mature / Specimen Trees:  Extensive  Moderate  Average  Limited  None  
 Area Available for Aboveground BMPs:  Extensive  Moderate  Average  Limited  None  
 Existing Cover of Potential Aboveground BMP Locations:  Grass  Landscaped  Gravel  Other Pervious  
 Pavement  Other Impervious

**UPPER PATUXENT RIVER WATERSHED RESTORATION ACTION STRATEGY (WRAS)  
FORM 2 -- Site Information (concluded)**

**Commercial / Institutional**

Islands Present:  YES  NO

Curb Present Around Island:  YES  NO

Ground Level of Island Relative to Pavement:  Above  Equal  Below

Island Landscaping:  Impervious  Bare Earth  Gravel  Grass  Mulch  Herbaceous Plants  Shrubs  
 Trees (<2 in. DBH)  Trees (2 - 6 in. DBH)  Trees (>6 in. DBH)

Trees have sufficient spacing to allow IMPs  YES  NO

Parking area that can be directed to potential treatment area with little grading: 100%

SITE SUMMARY	
WQ <sub>v</sub> (provided) :	Re <sub>v</sub> (provided):
Area Treated (ac) :	Impervious Area Treated (ac):
Area Treated (%) :	Impervious Area Treated (%):

**Photographs**

- No. 667 Description: looking southeast across west side of lot
- No. 668 Description: looking east across north side of lot
- No. 669 Description: looking south to visitors center across east side of lot
- No. 670 Description: looking northwest at northeast side of building
- No. 671 Description: looking east at north (front) side of building
- No. 672 Description: looking southeast at west side of building
- No. 673 Description: looking north from visitors center
- No. \_\_\_\_\_ Description: \_\_\_\_\_
- No. \_\_\_\_\_ Description: \_\_\_\_\_
- No. \_\_\_\_\_ Description: \_\_\_\_\_

**Comments** Site is currently treated by storm water wetland.

---



---



---



---



---

**UPPER PATUXENT RIVER WATERSHED RESTORATION ACTION STRATEGY (WRAS)  
FORM 2 -- Site Information**



667



668



669



670



671



672

**UPPER PATUXENT RIVER WATERSHED RESTORATION ACTION STRATEGY (WRAS)  
FORM 2 -- Site Information (concluded)**



673